

TRANSPORT LABEL



CARRYING

When moving the worktop, always carry vertically, minimum 2 persons, one on each side of the worktop.






2




STORAGE

Always store the packed worktop horizontally on even surface in order to acclimate at least 24 hours. Specially valid for solid wood worktops.







3



CLIMATE CONDITIONS

The worktop has to be stored and mounted in a room with stable temperature minimum 18 degrees Celsius.

